


**ATC-38 ERRATA**

(Applicable for reports sold or distributed before July 31, 2003)

**Database on the Performance of Structures Near Strong-Motion Recordings: 1994 Northridge California, Earthquake**

Page	Location	Change
Inside front cover	Cover illustration at the bottom of the page	Replace: “View of the NIST Universal Testing Machine, courtesy of the National Institute of Standards and Technology”  With: “Area map and exploded view of a typical strong-motion recording station location and the surrounding inspected buildings.”  (Note: Initial releases of report have the correct text.)
Page v	Fourth line from the bottom	Replace: “Appendix B: Follow-up Survey Information” With: “Appendix B: Northridge Earthquake Building Repair Survey”.
Page 47	Col. 1, Equation 4.1	Replace equation with the following:  $a_{rms} = \sqrt{\frac{1}{T_d} \int_0^{T_d} a(t)^2 dt}$
Page 48	Col. 1, Equation 4.1	Re-number equation to 4.2. Replace equation with the following:  $SI(\xi) = \int_{0.1}^{2.5} PSV(\xi, T) dT$
Page 226	Figure A-184	Replace figure with the following:  
Page 230	Col. 2, Line 5	Replace “association” with “associated”.